

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flasham.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

Note: Firmware 2.6.xx can NOT be upgraded to firmware 2.7.xx. If you wish to upgrade from firmware 2.6.xx to 2.7.xx, please send back the camera to LILIN for firmware upgrade.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for ZFR8122EX2, ZFR8122EX3, ZFR6422EX3, UHG1182E, UFG1122E, ZHR8182EX2 & ZHR6482EX2

Version 2.7.92.8848

1. Fixed the MQTT authenticating function.
2. Modified the way of display for HTTP POST.
3. Upgraded the ActiveX to 1.0.50.172 version.

Version 2.7.92 (svn6356)

1. Default is provide 4 sets of video streams simultaneously
2. File Recovery
3. Improved push service
4. Improved General page display
5. Improved SetVideoEncoderConfiguration message.
6. Support Milestone XProtect Professional 2017 R2, Version: 11.2a
7. Support RS-485 read, write function.
8. Support ONVIF Profile S certification.
9. Fixed NAV focus speed range to work as per new architecture °
10. Fixed NAV version 2.0.0.108 cannot control zoom in & zoom out
11. Fixed NAV zoom speed range to work as per new architecture °
12. Fixed bug: the default value is incorrect after updating model type
13. Fixed SYS_LOG_INFO PAGE UI color
14. Fixed GetVideoSources reply to daytime brightness error
15. Fixed ONVIF tool 17.12 TEARDOWN issue
16. Fixed when user change administrator account password, logged-in in Onvif will delete user's account resulting to unable to log in to device.
17. Modify the timezone setting to write the corresponding Nvram
18. Fixed when device name exceeds 40 characters, turn on the ODM will cause the camera to crash re-start.

Version 2.7.90 (2017/11/23)

1. Supported new stream method for S series.(new function)
2. Supported IVS 2.0 and IVS 2.1 for S series. (new function)
3. Supported TLS for SMTP function.
4. Supported SIP function.
5. Supported HTML5 video stream in the chrome, FireFox and safari browser.

- 6 Support search event log and improve event log.
- 7 Support MQTT function.
- 8 Support HTTPS for LILIN DDNS Server.
- 9 Add Push Service page for mobile phone.

Version 2.6.74 (2017/03/16)

1. Added support for new camera ZSR8122
2. Added focus and zoom speed for auto focus page.
3. Fixed HDR mode
4. Added Quick Zoom Wide feature for wider FOV

For technical support information, please contact:

LILIN ZenDesk at https://lilin.zendesk.com/anonymous_requests/new.

For sales information, please contact:

Michelle, International Sales Director, at
Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com