

Version 10.4.001.5669 (2024/09/30) for DS362, DS362A and DS362AW

1. Fixed the LED of the wide angle lens module does not light up when it is turned on.

Version 10.4.001.4931 (2024/01/18) for DS362

1. Added one set of Alarm Output for the hardware.
2. Added one set of Alarm Out in the smartevent.
3. Modified the default FPS to 11.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Michelle, International Sales Director, at
Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com