

## Release Note for LILIN NVR6208AE & NVR6216AE

Version 14.0.40.10892 (2025/12/04)

1. Fixed HTTPS certificate import function.
2. Added support for LPR 2.0 function (Taiwan license plates only).
3. Added support for event screenshot upload to NCC.
4. Added support for IP Scan screenshot function.
5. Fixed audio video synchronization issue during remote playback.
6. Fixed an issue where audio would not output after switching from multi channel to single channel playback and back to multi channel on the local end.
7. Fixed an issue with the settings page drop down menu and the ALARM > OUTPUT operation.
8. Fixed an issue with the NCC crashing when sending oversized event screenshots.
9. Fixed an issue with streaming decode output being output in HD whenever possible.
10. Fixed an issue where alarm text was not displayed when no alarm view output was configured.
11. Fixed an issue where enabling audio output during playback had no effect after muting in liveview on the local end.
12. Fixed an issue with alarm screenshot crashing.
13. Added support for multiple backup tasks.
14. Fixed a local backup crash.
15. Fixed an issue where the alarm sound icon did not return to normal after alarm sound ended.
16. Fixed an issue where the remote backup file list was not displayed, and the backup progress was not shown on the local end.
17. Fixed an issue where audio was not output when the selected channel exceeded the number of display channels in multi channel view on the local end.
18. Updated the allowed symbol range in password fields: ~!@#\$%^
19. Fixed incorrect available recording space information for estimated recording time in software RAID
20. In the PTZ settings' daisy-chain page, the daisy-chain data table contains incorrect information.
21. On the host side, under META DATA > Event, event playback shows abnormal timestamps after switching pages, causing playback to fail.
22. In HDMI Sync display mode, when enabling the auto-sequence (tour) function, the detection areas of two AI cameras are shown in the same split-screen position, which may cause system abnormalities and force a reboot.
23. Added a quick-clip backup function during playback.
24. Corrected the right-click menu on the local host so that available functions match the user' s permission level.
25. Fixed the issue where only the admin user could modify user permissions; users can only change their own passwords.
26. Fixed the issue where no recording data was displayed on the playback timeline when the user did not have alarm permissions.
27. Fixed an issue where, when the alarm sound output was set to Always, after an alarm was triggered and cleared, and then triggering it again produced no action.
28. Corrected the multi-language text and content for AI person, vehicles, and sensitivity (previously confidence level).
29. Network > FTP, added support for SFTP.
30. Fixed an issue where function options were not set according to user permissions.
31. Fixed an issue where account lockout function was not working.
32. Fixed an issue where the web interface could not display 5MP camera corridor mode video at 1620x2880 resolution.
33. Fixed an issue where the local interface could not display 5MP camera corridor mode video.1
34. Spot feature supported.

**For technical support, visit <http://lilin.zendesk.com>.**

**For sales information, please contact:**

Chris Hsu, Vice President, at

Email: [sales@meritlin.com](mailto:sales@meritlin.com)

Merit LILIN Enterprise Co., LTD.

No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,

New Taipei City 248, Taiwan (R.O.C.)

TEL: 886-2-2298-8988 FAX: 886-2-2298-9077

[www.meritlin.com](http://www.meritlin.com)