

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashssc327.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Version 13.0.001.6705 (2025/10/09)

- Fixed security issues.

Version 9.0.001.5245 (2024/05/24) for P5/Z5 series

- Added the operation timeout in the path "Setup > System > User > Operation Timeout".
- Fixed the directory can't be created by using the FTP feature.
- Fixed the webpage timeout issue.
- Fixed the camera can't be scanned by using the ODM software.
- Fixed the live image will be disconnected via the app if the camera password is changed.

Version 9.0.001.2486 (2021/04/20) for P5/Z5 series

- Fixed using the webpage recording issue
- Fixed using the motion recording to the SD card, the SD card continues to record and doesn't stop.
- Modified the viewer permission.
- Fixed the 2MP cameras with a high shutter speed that the live image becomes red color.

Version 9.0.001.2262 (2020/12/03) for P5/Z5 series

- Fixed the HTTPS certificate issue.
- Fixed the DHCP to Static IP issue if changing it from IPScan tool that the camera can't be connected.

Version 9.0.001.1599 (2020/5/26) for P5/Z5 series

- Fixed autofocus does not work during zooming in/out when operating NAV.
- Fixed cannot create an account when ODM is creating it.
- Fixed when recording with Micro SD card, the SD card will automatically unload after recording for around three days, and cannot be loaded.
- Fixed when NAV uses reboot device function, the device does not reboot.
- Fixed Micron 128G memory card cannot be mounted.
- Modified ActiveX, IVS blue detection frame's border lines became thicker and font size became bigger.
- Modified when ODM create a new account and the created account does not meet the password policy, will display an error. But the warning message will display "Password" instead of "Password too weak".
- Fixed when on the advanced image or the basic image page, the device is in AUTO mode when it should be fixed in day mode or night mode.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Michelle, International Sales Director, at
Email: mma@meritlin.com.tw.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlin.com