

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashnt9852x-s.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for **Z6R6482X3, P6R6382E2, Z6R8982X3 and P6R8882E2**

Version 13.0.001.4433 (2023/07/20)

- Added the feature to support QR code in the DDNS webpage.
- Supported using the APP for single playback and continuous playback.
- Supported SD card pre-recording time from 1 to 5 seconds and the default is set as 1 second.

Version 13.0.001.3724 (2022/10/06)

- Re-assigned the RAM usage.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com