

LILIN P6W/Z6W (5MP) Release Note

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashnt98529l2-s.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for P6W9452E2_Z6W9552X3

Version 13.0.002.6819 (2025/11/14)

1. Removed Bypass Logon from the webpage and changed the version number to 13.0.002 for easier version differentiation.
2. Fixed the issue where color mode fails to switch in night mode.
3. Fixed an issue where multiple entries could not be added in IP/MAC Address Filtering.
4. Fixed an issue where the shutter value reverted to the default value when changing the FPS.
5. Added a Push page that displays the device token when a device connects.
6. Fixed the push list display.

Version 13.0.001.6686 (2025/10/09)

1. Fixed security issues.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Mr. Chris Hsu, Vice President, at
Email: sales@meritlilin.com.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com