

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashnt9856x-s.bin
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for V1R9522E2J-LTE

Version 14.0.002.7077 (2026/02/11)

1. Fixed the information on the Network page can't be modified.

Version 14.0.002.6868 (2025/12/01)

1. Using a 4G network card with myLILIN APP on a mobile phone. After selecting "Refresh" on the IP camera's push service page, the push list disappears. The list only reappears after the push service option is selected again.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Mr. Chris Hsu, Vice President, at
Email: sales@meritlilin.com.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com