

Release Note for LILIN DHD032

Version 1.0.28.3858

1. Fixed the speed test failure issue.

Version 1.0.26.3858

1. Fixed the UPnP search memory leak issue.
2. Fixed the DH032 ONVIF device table.

Version 1.0.24.3655

1. Fixed the upload bandwidth speed to the cloud incorrectly.
2. Fixed the reset button no response.

Version 1.0.20.3399

1. Modified: Device table checkbox position moved to the far left.
2. Modified: Device table displays the selected devices quantity.
3. Added: Automatically synchronize the device name, IP, Port of the LILIN device.
4. Added: Cloud can delete managed device.
5. Added: Add get MAC device button (can get the MAC address of the ONVIF device).
6. Added: Automatically check if LILIN camera needs to restart function.
7. Added: Account added whether enable automatically detect camera restart.
8. Added: Event log added restart log.
9. Added: ONVIF device can be software reboot. Also, if it is in PoE switch, it can be power off and restart (the account password must be set correctly to obtain MAC first).
10. Added: Edimax smart plug (SP2101W_V2) search and power reset.
11. Added: Avsysio plug (9255) search and power reset.
12. Added: Editable PoE switch name.
13. Added: Video loss channel send to cloud.
14. Added: Smart HDD error send to cloud.
15. Added: Send DH032 IP address to cloud.
16. Added: Cloud uploading and downloading bandwidth test.

For technical support, visit <http://lilin.zendesk.com>.

For sales information, please contact:

Michelle, International Sales Director, at

Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.

No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,

New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlin.com