

Release Note for DHD6216A

DHD6216A V.12.0.42.11188

1. Added a quick clip backup function during local playback.
2. Fixed a local backup crash.
3. Modified AHD 3M encoding resolution to 2048x1536.

DHD6216A V.12.0.40.10923

1. Fixed the jagged edges in the camera's CVBS video output.
2. Fixed the issue where the DO output was triggered during startup.
3. Fixed the motion detection area setting function.
4. Fixed incorrect UTC command behavior when using different protocols (AHD/TVI/CVI/CVBS) and resolutions (5M/4M/2M/SD).
5. Fixed the black border on the left side when outputting AHD 4M25/4M30.
6. Fixed the hardware reset function not working during initial setup and login.
7. Fixed the issue where the host device could not display 5MP camera corridor mode video.
8. Fixed the issue where playback FPS information was not displayed.

DHD6216A V.12.0.36.9903

1. Fixed the issue where a "Warning" dialog box is displayed even when settings are not changed.
2. Updated multi-language support.
3. Fixed CAMERA>GENERAL related settings and add log records of HTTP requests.
4. Added and modified RECORD>GENERAL settings.
5. Fixed BACKUP>Mulit-View HD (4CH) related settings.
6. Fixed the option values and related settings of Local Imaging Setting.
7. Updated and fixed IPv6 related settings.
8. Fixed snapshot related issues.
9. Fixed getpbstream CGI error.
10. Fixed the issue where the title of the remote live view for the unauthorized channel is not updated.

For technical support information, please contact:

LILIN ZenDesk at https://lilin.zendesk.com/anonymous_requests/new.

For sales information, please contact:

Chris Hsu, Vice President, at

Email: sales@meritlilin.com

Merit LILIN Enterprise Co., LTD.

No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,

New Taipei City 248, Taiwan (R.O.C.)

TEL: 886-2-2298-8988 FAX: 886-2-2298-9077

www.meritlilin.com