

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flasham.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Version 3.2.92.9073 (2020/06/20)

1. Fixed the day and night switch problem on Schedule mode. When switched from day to night, the image will become red before switching to black & white.
2. Added model 671 for IPC0522E6.
3. Fixed log will display privacy mask disable when LDC is enabled.
4. Fixed log will record alarm detection setting when modifying the advanced settings of intercom.
5. Fixed there is no response when clicked on Hard Reset, when using ODM connection.
6. Fixed after logging in ODM, can add, modify or delete user information. When adding an operator without administrator rights or use ODM to add an operator.
7. Fixed when using ODM connection, the bitrate of En3 resolution (1280*960 and 1280*720) can be set to 12M and webpage EN3 maximum limit is only 5M.
8. Fixed cannot connect to webpage after using ODM to modify the HTTP port number.
9. Fixed the day and night switching issue.
10. Fixed when mount SD Card, and execute reboot or Load Default, it will automatically Unmount and can't be Mount. Need to re-plug to read the SD Card.
11. The IPC0522E2 default setting is LDC On and IPC0522E6 default setting is LDC Off.

Version 3.2.88 (2017/10/26)

1. Added 1 second option of alarm output dwell time in IPC0522.
2. Fixed SIP function memory leak issue.
3. Fixed SIP function high CPU issue.
4. Added reboot schedule function in IPC0522.
5. Improved image HDR performance
6. Supported TLS for SMTP function.
7. Supported HTML5 video stream in the chrome, firefox and safari browser.(HTML5 stream support 1080P)
8. Supported search event log and improve event log.
9. Supported MQTT function.
10. Supported Smart H.264 video stream.
11. Supported AAC audio for RTSP stream.
12. Supported LDC function.
13. Supported SAMBA function.
14. Improved network performance.
15. Added default function in the Maintenance page.
16. Added Push Service page for mobile phone.
17. Supported HTTPS for LILIN DDNS Server.

For technical support information, please contact:

LILIN ZenDesk at https://lilin.zendesk.com/anonymous_requests/new.

For sales information, please contact:

Michelle, International Sales Director, at

Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.

No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,

New Taipei City 248, Taiwan (R.O.C.)

TEL: 886-2-2298-8988 FAX: 886-2-2298-9077

www.meritlilin.com