

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashnt98529ac2-s.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for P6R3752E2

Version 13.0.001.5066 (2024/05/22)

1. Added a new web page time zone setting to separate London as an option.
2. Fixed the mechanism for deleting files when the SD card is in overwrite, changing it to delete the one-hour directory.
3. Fixed the issue of requiring to log in twice for iPhone web page connection.
4. Added warning messages for SD format ext4 / The default format of SD card is ext4.
5. Added the ability to double-click on the EDGE home page image to zoom in/out, Quality Basic/Quality Advance/Auto Focus.
6. Fixed the issue of multicast audio data not being transmitted.
7. Added "Load Default" option on Maintenance page.
8. Added SD card pre-recording as 5 seconds.
9. Added the LPKG display the system resources.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Mr. Chris Hsu, Vice President, at
Email: sales@meritlilin.com.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com