

PS3108C/PS3188C/PS3268C PoE switches release note

Version 6.54.3603

- Fixed the compatibility issue when connect it with DH032.

Version 6.54.3199

- Fixed the MAC address displayed incorrectly.
- Fixed the message “poe device #1 not found / poe device #2 not found” is displayed at startup.
- Fixed the switch auto reboot issue when the E series cameras are connected.

For technical support information, please contact:

LILIN ZenDesk at https://lilin.zendesk.com/anonymous_requests/new.

For sales information, please contact:

Michelle, International Sales Director, at
Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com