

Version 3.2.94.8917 (2024/01/15) for PSR5520EX25_30

1. Fixed the audio output issue.

Version 3.2.94.8915 (2020/04/24) for PSR5520EX25_30

1. Fixed the 180 degrees pan issue when enabling the autopan via NVR or keyboard.
2. Fixed if the password contains @ and /, the speed dome doesn't have any response with the right click on the mouse.
3. Fixed the user permission incorrectly issue.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Michelle, International Sales Director, at
Email: mma@meritlilin.com.tw.

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com