

Update firmware from web interface:

1. Login into the IP Camera via web browser.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashS3LM.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Released for the LPR series cameras below

Z2R8952LPR-H_Z2R8952LPR3-H_Z2R8952LPR-HT_Z2R8952LPR3-HT

Version 7.1.94.10800

1. Upgraded openssl version to 1.0.2r to support tls1.2.
2. Fixed if resetting network interface when network cable has been plugged in that network status is down.
3. Fixed SMTP service issue.
4. Fixed the DDNS connection issue.
5. Fixed the multicast setting issue.
6. Fixed if clicking day mode or night mode on the quality basic or quality advanced page, the day and night switching and motion will automatically become invalid.