

Update firmware from web interface:

1. Login into the IP Camera via IE.
2. Click on Configure->System->Firmware Update
3. Click on "Browse" button to locate the firmware file, flashS3LM.bin.
4. Click on "OK" button.
5. Wait the web interface to be reloaded again.

WARNING!

YOU DO NOT HAVE TO UPDATE YOUR DEVICE TO THE LATEST FIRMWARE. HOWEVER, THE LATEST FIRMWARE MAY IMPROVE A DEVICE'S PERFORMANCE AND ADD ADDITIONAL FEATURES. THERE IS A RISK OF FAILURE WHEN UPDATING A FIRMWARE, THIS INCLUDES POWER FAILURE, LOW BANDWIDTH OR BROKEN FLASH DISK. A FAILED FIRMWARE UPDATE WILL REQUIRE RETURNING THE DEVICE BACK TO YOUR ORIGINAL PROVIDER FOR REPAIR.

Version 8.1.94.10589 (2022/12/27) for Z3R8922LPR-H and Z3R8922LPR-HT

1. Fixed using Chrome in Ubuntu no live view display.
2. Fixed the bypass logon with the black screen in the live image.
3. Fixed the digital input issue in smart event.

For technical support information, please contact:

LILIN ZenDesk at <http://lilin.zendesk.com>.

For sales information, please contact:

Michelle, International Sales Director, at
Email: [mma@meritlilin.com.tw](mailto:mmma@meritlilin.com.tw).

Merit LILIN Enterprise Co., LTD.
No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,
New Taipei City 248, Taiwan (R.O.C.)
TEL: 886-2-2298-8988 FAX: 886-2-2298-9077
www.meritlilin.com