

Release Note for LILIN NVR7 Series

Version 13.0.38.10018 (2024/08/26)

1. The web interface supports nine-split screen.
2. Fixed the playback function button; changed the multiplier button to a dropdown menu and added a 5-second rewind function.
3. Fixed the issue when the snapshot directory does not exist in the flash drive, it causes the local device to crash when taking pictures.
4. Fixed a crash issue caused by changing P2P or network settings in the setup wizard.
5. Added support for LILIN ToF cameras.
6. Added support for disabling USB flash drives.
7. Fixed abnormal METADATA barcode reader data issue.
8. Fixed METADATA sequence server reading issue.
9. Added support for IPv6, allowing connection to NVRs and cameras, and providing RTSP connections for cameras and provide streaming.
10. Added support for a "Forgot Password" function.
11. Added support for an AI counter function.
12. Added support for setting the resolution of network cameras.
13. Added support for setting page option description in multiple languages.
14. Added connection information and the function of connecting to a network camera in the Camera Settings > General Settings page.
15. Added an "Apply to All Channels" function in the Recording Settings > General Settings.
16. Fixed the issue where the camera cannot obtain JPEG images using HTTPS connection.
17. Fixed the issue of unable to obtain LILIN camera SNAP images.
18. Fixed the right-click screenshot function on the local device.
19. Fixed the issue where remote playback does not apply channel hiding settings.
20. Fixed an issue where the remote live view did not update hidden channel names.
21. Added QR Code to the P2P page in the setup wizard.
22. On the Setting Wizard completion page, set no longer using the Setting Wizard as the default option.
23. Modified "Save Recording" in Recording Settings > General Settings to "Weighted Recording."
24. Added "Network Disconnected" option in Alarm Settings > Output Settings > System Events.
25. Added "Network Disconnected" and "Recording Stopped" messages in the latest messages on the local device.
26. Fixed the display time point issue of the AI counter icon on the web interface.
27. Fixed the issue that the count content of P6 camera is not displayed.
28. Updated the default NTP synchronization interval to 24 hours.
29. Modified the local screenshot output format to JPG.

Version13.0.34.9430(2023/10/11)

1. Added user permissions for LIVE/PLAYBACK on each channels.
2. Added LILIN IP camera DO control on the web page.
3. Fixed integration issues with LILIN AI cameras and performance adjustments (requires camera and LPKG firmware).
4. Fixed the restore default value of camera image settings does not match with the camera side.
5. Added a LILIN event cloud push account detection mechanism.
6. Added Slovak, Bulgarian, and Danish languages supported.
7. Fixed the abnormal issues in the web playback event filter and list when the time format is not YYYY/MM/DD.
8. Fixed the METADATA keyword search function in the event table.
9. Updated the backup manager to version 1.1.0.8 to fix the incomplete backup file issues via FTP.
10. Fixed the AI event category name and remove the “other (Uncategorized)” options.
11. Fixed the ONVIF image setting function.

For technical support, visit <http://lilin.zendesk.com>.

For sales information, please contact:

Mr. Chris Hsu, Vice President, at

Email: sales@meritlilin.com

Merit LILIN Enterprise Co., LTD.

No.20, Wu-Gong 6th Rd., New Taipei Industrial Park, Wu-Gu Dist.,

New TaipeiCity 248, Taiwan (R.O.C.)

TEL: 886-2-2298-8988FAX: 886-2-2298-9077

www.meritlilin.com